

URM37 V3.2 Ultrasonic Sensor Manual

2008-09-22

### Introduction

URM37 V3.2 Ultrasonic Sensor uses an industrial level AVR processor as the main processing unit. It has a temperature correction which is very unique of its kind.

# **Specification**

Power: +5V

Current: <20mA

Working temperature: -10  $^{\circ}$ C  $\sim$  +70  $^{\circ}$ C

Detecting range: 4cm-5m

Resolution: 1cm Interface: RS232,

PWM Servo control: One servo control output

Operating Mode: Serial (PWM) passive control mode; Autonomous Mode; On/OFF Mode

Temperature sensor: 12 bits reading from serial port

Size: 22mm  $\, imes\,$  51 mm

Weight: 30g




Figure 1: URM37 V3.2 Beam Width




Figure 2: URM37 V3.2 Pin Definition

- 1: +VCC -+5V Power
- 2: GND -Ground
- 3: RST -Reset
- 4: PWM PWM Output 0-25000US, Every 50US represent 1cm
- 5: MOTO Servo control signal output
- 6: **COMP/TRIG COMP** On/OFF mode, when the detecting distance is smaller than a pre-set value, this pin pulls low. **TRIG** PWM or RS232 trigger pin
- 7: PWR\_ON Enable pin, enable the sensor when high
- 8: RXD RS232,TTL communication
- 9: TXD -RS232,TTL communication

Working mode can be changed by writing 0x00, 0x01 or 0x02 to EEPROM through serial port.

#### Mode 1: Serial passive control mode

Under this mode, the sensor is always waiting for command from serial port. Every time it receives a command, it will return the distance and wait for the next command. The degree in the command will be used to control a servo motor to rotate corresponding degree.

#### Mode 2: Autonomous mode

Under this mode, the sensor will make a sensor reading every 25ms and compare the reading with a threshold (pre-set, user is able to define this value by writing EEPROM), if the reading is equal or smaller than the threshold, pin COMP/TRIG will have low output. In the meantime, pin PWM will output the distance reading, every 50us low level stands for 1cm, by counting the number of these pulses, the distance can be calculated. This mode can be simply used as an ON/OFF switch.

#### Mode 3: PWM passive control mode

Under this mode, a low pull on pin COMP/TRIG will trigger a sensor reading. The width of the pulse is proportional to the servo rotating degree. After a successful sensor reading, Pin PWM will output pulses, every 50us represents 1cm. If the reading is invalid, a 50000us pulse will be returned.

### **RS232 control protocol**

RS232 setting: Port rate: 9600; Parity: none; Stop bit: 1

Command: Control command consists of four bits, command+data0+data1+sum. Sum=Low 8 bit of the sum of command+data0+data1.

Command Format	Function	Description
0x11+NC+NC+Sum (Sample: 0x11 0x00 0x00 0x11)	Enable 16 bit temperature reading	Reading the temperature, the return data format will be:  0x11+High(temperature)+Low(temperature)+SUM If the temperature is above 0, the first four bits of High will be all 0. If the temperature is below 0, the first four bits of High will be all 1. The last 4 bits of High together with the Low bits stands for 12bits temperature. The resolution is 0.1. When the reading is invalid, it returns  0x11+0xFF+0xFF+SUM
0x22+Degree+NC+SUM (Sample: 0x22 0x00 0x00 0x22)	Enable 16 bit distance reading	The degree in the command is used to control a servo motor to rotate corresponding degree.  Degree: 0-46 stands for 0-270 degrees, for example, 3 stands for 18 degrees. Return data format will be: 0x22+High(distance)+Low(distance)+SUM。 When the reading is invalid, it returns 0x22+0xFF+0xFF+SUM
0x33+Add+NC+SUM	Enable internal EEPROM reading	Return data will be 0x33+Add+Data+SUM。

0x44+Add+Data+SUM	Enable internal EEPROM writing	Written data can only from 0-255.  Address 0x00-0x02 is used to configure the mode.  0x00 – threshold distance (Low)  0x01 – threshold distance (High)  0x02 – Operation Mode (0xaa for autonomous mode)  (0xbb for PWM passive control mode)
		(0xbb for PWM passive control mode)  The return data format will be:  0x44+Add+Data+SUM。

Note: NC stands for any data,  $\,$  SUM stands for sum, Add stands for address  $_{\circ}$ 

1. PWN\_ON must be set to High to enable sensor.

# Servo control command reference table:

DEC	0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
HEX	0	01	02	03	04	05	06	07	08	09	0A	0B	0C	0D	0E	0F
Degree	0	6	12	18	24	29	35	41	47	53	59	65	70	76	82	88
DEC	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
HEX	10	11	12	13	14	15	16	17	18	19	1A	1B	1C	1D	1E	1F
Degree	94	100	106	112	117	123	129	135	141	147	153	159	164	170	176	182
DEC	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	
HEX	20	21	22	23	24	25	26	27	28	29	2A	2B	2C	2D	2E	
Degree	188	194	200	206	211	217	223	229	235	241	247	252	258	264	270	

