MPLAB IDE

The Extended CPU Mode configuration bit is enabled, but the program that was loaded was not built using extended CPU instructions. Therefore, your code may not work properly.

OK